
Speaker name Job title, date, legal entity

layout feedback April 19th


QUALCOMM[®]



Stackup change


We switched to different PWB manufacturer.

Need to update all the control impedance traces in all the layers




XIF Trace on Layer 3 – fill Layer 2


Route on L3 with L2 full reference above (ref layers L2 and L4) Ned stackup allow this new routing



Netlist change

Fix open nets – I removed several components





Silk screen

Make the bottom side label smaller to fit the

